




Overview: Part of spill impact on 8" Umuechem-Nkpoku Pipeline Right of Way at Omusele. Picture was taken during Joint Investigation of 20th February 2018.



Close-up: Illegal fittings on 8" Umuechem-Nkpoku Pipeline at Omusele. Picture was taken during Joint Investigation of 20th February 2018.