




Overview: Part of spill impact on 12" Imo River – Ogale Pipeline Right of Way at Kom-Kom. Picture was taken during Joint Investigation of 22nd February 2018.



Close-up: Illegal fitting on 12" Imo River – Ogale Pipeline at Kom-Kom. Picture was taken during Joint Investigation of 22nd February 2018.