




**Overview:** Part of spill impact on 20''Rumuekpe-Nkpoku Pipeline Right of Way at Omuigwe-Aluu. Picture was taken during Joint Investigation of 15<sup>th</sup> February 2018.



**Close-up:** Illegal fitting on 20''Rumuekpe-Nkpoku Pipeline at Omuigwe-Aluu. Picture was taken during Joint Investigation of 15<sup>th</sup> February 2018.