



Overview: Part of spill impact on 4" Otamiri Well5LS Flowline Right of Way at Abara. Picture was taken during Joint Investigation of 27<sup>th</sup> February 2018.



Close-up: Hacksaw cut on 4" Otamiri Well5LS Flowline at Abara. Picture was taken during Joint Investigation of 27<sup>th</sup> February 2018.