



**Overview:** Part of spill impact on 24" Trans-Escravos Pipeline Right of Way at Sokebolou. Picture was taken during Joint Investigation of 2<sup>nd</sup> March 2018.



**Close-up:** Illegal fitting on 24" Trans-Escravos Pipeline at Sokebolou. Picture was taken during Joint Investigation of 2<sup>nd</sup> March 2018.