



Overview: Part of spill impact on 36inch Nkpoku Bomu Pipeline at Atali . Picture was taken during Joint Investigation of 27<sup>th</sup> February 2020.



Close-up: 3nos illegal connections( crude theft) installed at 12 o'clock position on 36inch Nkpoku Bomu Pipeline at Atali . Picture was taken during Joint Investigation of 28<sup>th</sup> February 2020.