



**Overview:** Part of spill impact on 4'' Imo River Well 43T Flowline at Igiriukwu. Picture was taken during Joint Investigation of 3<sup>rd</sup> March 2020.



**Close-up:** Hacksaw cut from 9 -3 o'clock position on 4'' Imo River Well 43T Flowline at Igiriukwu. Picture was taken during Joint Investigation of 3<sup>rd</sup> March 2020.