



Overview: Part of spill impact on 36" Npoku-Bomu pipeline right of way at Eneka. Picture was taken during Joint Investigation of 20th January 2012.



Close-up: 1st set of Illegal fittings on 36" Npoku-Bomu pipeline at Eneka. Picture was taken during Joint Investigation of 21st January 2012.



Overview: 2nd set of Illegal fittings on 36" Npoku-Bomu pipeline at Eneka. Picture was taken during Joint Investigation of 21st January 2012.