



Overview: Part of spill impact on 8" Cawthorne Channel2 pipeline at Tigerkiri. Picture was taken during Joint Investigation of 21<sup>st</sup> January 2012.



Close-up: Illegal fitting on 8" Cawthorne Channel2 pipeline at Tigerkiri. Picture was taken during Joint Investigation of 21<sup>st</sup> January 2012.