



Overview: Farmland burnt by fire due to spill on 8" Umuechem-Nkpoku pipeline at Omunwei, Igwuruta. Picture was taken during Joint Investigation of 26<sup>th</sup> January 2012.



Close-up: Illegal fitting on 8" Umuechem-Nkpoku pipeline at Omunwei, Igwuruta. Picture was taken during Joint Investigation of 26<sup>th</sup> January 2012.