



Overview: Part of spill impact on 24" Nkpoku-Bomu pipeline right of way at Sime Picture was taken during Joint Investigation of 11th January 2013.



Close up: Spill due to drilled hole on 24" Nkpoku-Bomu pipeline at Sime Picture was taken during Joint Investigation of 11th January 2013.