



Overview: Part of spill impact on 10" Diebu Creek – Nun River pipeline right of way at Onyoma. Picture was taken during Joint Investigation of 5th January 2013.



Close up: Hacksaw cut on 10" Diebu Creek – Nun River pipeline at Onyoma. Picture was taken during Joint Investigation of 5th January 2013.



Close up: Depression on 10" Diebu Creek – Nun River pipeline at Onyoma.
Picture was taken during Joint Investigation of 5th January 2013.



Close up: Hacksaw cut on 10" Diebu Creek – Nun River pipeline at Onyoma.
Picture was taken during Joint Investigation of 6th January 2013.