



Overview: Spill impact on Cawthorne Channel1 Well9 Right of Way at Captainkiri. Picture was taken during Overfly of 26th January 2015.



Close-up: Spill point on Cawthorne Channel1 Well9 at Captainkiri. Picture was taken during Joint Investigation of 28th January 2015.