



Overview: Part of spill impact on 30" Nembe Creek Pipeline Right of Way at Opomakiri. Picture was taken during Joint Investigation of 26th January 2015.



Close-up: Illegal fitting on 30" Nembe Creek Pipeline at Opomakiri. Picture was taken during Joint Investigation of 26th January 2015.