



Overview: No observable impact on water at Nembe1 Well11L 4" Flowline Right of Way at Nembe Creek. Picture was taken during Joint Investigation of 29th January 2015.



Close-up: Bubbles observed at spill point on Nembe1 Well11L 4" Flowline at Nembe Creek. Picture was taken during Joint Investigation of 29th January 2015.