




Overview: Part of spill impact on 28" Nkpoku – Bomu Pipeline Right of Way at K-Dere. Picture was taken during Joint Investigation of 10th January 2016.



Close-up: Illegal fitting on 28" Nkpoku – Bomu Pipeline at K-Dere. Picture was taken during Joint Investigation of 10th January 2016.