



Close-up: Leak point on 28" Bomu-Bonny Pipeline (Opobo Riser) at Owokori. Picture was taken during Joint Investigation of 8th January 2016.