



Overview: Part of spill impact on Soku Well 21L Flowline at Russia-Soku. Picture was taken during Joint Investigation of 18th January 2016.



Close-up: Hacksaw cut on Soku Well 21L Flowline at Russia-Soku. Picture was taken during Joint Investigation of 18th January 2017.