



Overview: Part of spill impact 6" Obigbo North – Ogale pipeline right of way at Ogale. Picture was taken during Joint Investigation of 5th July 2013.



Close up: Illegal fitting on 6" Obigbo North – Ogale pipeline at Ogale. Picture was taken during Joint Investigation of 5th July 2013.