



Overview (Point A): Part of spill impact on 12" Adibawa-Okordia pipeline right of way at Ikarama. Picture was taken during Joint Investigation of 19th July 2013.



Close up (Point A): Hacksaw cut on 12" Adibawa-Okordia pipeline at Ikarama. Picture was taken during Joint Investigation of 19th July 2013.



Overview (Point B): Part of spill impact on 12" Adibawa-Okordia pipeline right of way at Ikarama. Picture was taken during Joint Investigation of 20th July 2013.



Close up (Point B): Hacksaw cut on 12" Adibawa-Okordia pipeline at Ikarama. Picture was taken during Joint Investigation of 20th July 2013.