



Close up: Illegal fitting on 24" Bomu-Bonny Trans Niger pipeline at Otokomabie/Oloma. Picture was taken during Joint Investigation of 18th July 2013.