




Overview: Part of Spill Impact on 24" Trans Ramos Pipeline Right of Way at Odimodi. Picture was taken during Joint Investigation of 21st September 2016.



Close-up: Inward dent and tear on 24" Trans Ramos Pipeline at Odimodi. Picture was taken during Joint Investigation of 21st September 2016.