



Overview: Part of spill impact on Yokri Well 113T Flowline at Obotobo I & II. Picture was taken during Joint Investigation of 20th July 2016.



Close-up: Position of stolen 3" plug valve on Yokri Well 113T Flowline at Obotobo I & II. Picture was taken during Joint Investigation of 20th July 2016.