




Overview: Part of spill impact on 28" Nkpoku - Bomu Pipeline at Gio – Kporghor. Picture was taken during Joint Investigation of 12th July 2016.



Close-up: Tear/inward dent on 28" Nkpoku - Bomu Pipeline at Gio – Kporghor. Picture was taken during Joint Investigation of 12th July 2016.