



Overview: Part of spill impact on 12" Imo River 2–Ogale Pipeline at Umuedeokwara. Picture was taken during Joint Investigation of 2nd August 2016.



Close-up: Illegal fitting on 12" Imo River 2–Ogale Pipeline at Umuedeokwara. Picture was taken during Joint Investigation of 2nd August 2016.