



Overview: Part of spill impact on 16" Egbema-Assa Pipeline at Obile. Picture was taken during Joint Investigation of 18th August 2016.



Close-up: Drilled hole on 16" Egbema-Assa Pipeline at Obile. Picture was taken during Joint Investigation of 18th August 2016.