




Overview: Part of spill impact on 24" Bomu-Bonny Pipeline at Mogho. Picture was taken during Joint Investigation of 24th July 2018.



Close-up: Illegal Fitting on 24" Bomu-Bonny Pipeline at Mogho. Picture was taken during Joint Investigation of 24th July 2018.