



Overview: Part of spill impact on 24" Nkpoku-Bomu Pipeline Right of Way at Sime. Picture was taken during Joint Investigation of 7<sup>th</sup> August 2018.



Close-up: Locally fabricated clamp on 24" Nkpoku-Bomu Pipeline at Sime. Picture was taken during Joint Investigation of 8<sup>th</sup> August 2018.