


Overview: Part of spill impact on 20'' Kolocreek - Rumuekpe Pipeline Right of Way at Okoma. Picture was taken during Joint Investigation of 25th July 2019.



Close-up: Plugged Illegal fitting on 20'' Kolocreek - Rumuekpe Pipeline at Okoma. Picture was taken during Joint Investigation of 25th July 2019