




Overview: Part of spill impact on 20'' Kolocreek - Rumuekpe Pipeline Right of Way at Okoma. Picture was taken during Joint Investigation of 1st August 2019.



Close-up: Leaking Illegal fitting on 20'' Kolocreek - Rumuekpe Pipeline at Okoma. Picture was taken during Joint Investigation of 2nd August 2019.