




Overview: Part of spill impact on 10" Diebu - NunRiver Pipeline Right of Way at Onyoma-Ekowe. Picture was taken during Joint Investigation of 28th July 2019.



Close-up: Bomb Blast on 10" Diebu – NunRiver Pipeline at Onyoma-Ekowe. Picture was taken during Joint Investigation of 28th July 2019