


**Overview:** Part of spill impact on 14" Okordia - Rumuekpe Pipeline Right of Way at Ikarama. Picture was taken during Joint Investigation of 30<sup>th</sup> July 2019.



**Close-up:** Internal Corrosion on 14" Okordia - Rumuekpe Pipeline at Ikarama. Picture was taken during Joint Investigation of 30<sup>th</sup> July 2019



Close-up: Internal Corrosion on 14" Okordia - Rumuekpe Pipeline at Ikarama. Picture was taken during Joint Investigation of 30<sup>th</sup> July 2019