



Overview: Part of spill impact on Nun River Well15S flowline right of way at Onyoma. Picture taken during Joint Investigation of 11th July, 2011



Close-up: Spill due to drilled hole on Nun River Well15S flowline at Onyoma. Picture taken during Joint Investigation of 11th July, 2011