



Overview: Part of spill impact on 10" Ekulama2 delivery line at Ekulama. Picture taken during Joint Investigation of 12th June, 2011



Close-up: Spill due to tear on 10" Ekulama2 delivery line at Ekulama. Picture taken during Joint Investigation of 12th June, 2011