



Overview: Raging fire on 24" Bomu-Bonny Pipeline at Bodo (Ogoni) . Picture taken during Joint Investigation of 10<sup>th</sup> June, 2011



Overview: Another view of fire on 24" Bomu-Bonny Pipeline at Bodo (Ogoni).



Close-up: Spill due to cut on 24" Bomu- Bonny Pipeline at Bodo (Ogoni). Picture taken during Joint Investigation of 10<sup>th</sup> June, 2011.