



Overview: Part of spill impact on 8" Isimiri pipeline right of way at Umuaghala. Picture taken during Joint Investigation of 28th June, 2011



Close-up: Illegal fitting on 8" Isimiri pipeline right of way at Umuaghala. Picture taken during Joint Investigation of 1st July, 2011