



Overview: Part of the spill impact on Okordia-Rumuekpe pipeline and Akalamini riser at Akalamini. Picture taken during Joint Investigation of 20th June, 2011



Close-up: Illegal fittings on Okordia-Rumuekpe pipeline and Akalamini riser at Akalamini. Picture taken during Joint Investigation of 20th June, 2011



Close-up: Illegal fittings on Okordia-Rumuekpe pipeline and Akalamini riser at Akalamini. Picture taken during Joint Investigation of 20th June, 2011