



Overview: Extent of the spill incident impact on 24" Nkpoku-Bomu Pipeline at Biara (Ogoni).
Picture taken during Joint Investigation of 12th June, 2011



Close-up: Spill due to cut on 24" Bomu-Nkpoku Pipeline at Biara (Ogoni). Picture taken
during Joint Investigation of 12th June, 2011.