



Overview: Part of extent of the spill incident impact on 24" Nkpoku-Bomu Pipeline at Bera (Ogoni). Picture taken during Joint Investigation of 13th June, 2011



Close-up: Spill due to cut on 24" Bomu-Nkpoku Pipeline at Bera (Ogoni). Picture taken during Joint Investigation of 13th June, 2011.