




Overview: Part of the spill impact on Cawthorne channel2 Well 32S flowline right of way at Mbiama. Picture taken during Joint Investigation of 28th June, 2011



Close-up: Spill due to hacksaw cut on Cawthorne channel2 Well 32S flowline at Mbiama. Picture taken during Joint Investigation of 29th June, 2011.