



Overview: Part of extent of the spill incident impact on 28'' Bomu-Bonny Pipeline at Bodo (Ogoni) . Picture taken during Joint Investigation of 11<sup>th</sup> June, 2011



Close-up: Spill due to cut on 28'' Bomu- Bonny Pipeline at Bodo (Ogoni). Picture taken during Joint Investigation of 11<sup>th</sup> June, 2011.