



Overview: Part of the spill impact at Olomoro compressor station 2 at Olomoro. Picture taken during Joint Investigation of 16th June, 2011



Close-up: Closeup of sump pit chamber and sump pit at Olomoro compressor station 2 at Olomoro. Picture taken during Joint Investigation of 16th June, 2011