



Overview: Part of extent of the spill incident impact on 28 inch Bomu-Bonny Trans Niger pipeline at Mogho. Picture taken during Joint Investigation of 11th June, 2011



Close-up: Leak point on 28 inch Bomu-Bonny Trans Niger pipeline at Mogho. Picture taken during Joint Investigation of 11th June, 2011.