



Overview: Oil sheen observed on Belema Well9T Wellhead Right of Way at Belema. Picture was taken during Joint Investigation of 13<sup>th</sup> June 2014.



Close-up: Original position of control unit removed from Belema Well9T Wellhead at Belema. Picture was taken during Joint Investigation of 13<sup>th</sup> June 2014.