



Overview: Booms enclosing Tunu Well 7T Wellhead Slot at Agbidiama. Picture was taken during Joint Investigation of 29<sup>th</sup> June 2017.



Overview: Part of spill impact on Tunu Well 7T Wellhead at Agbidiama. Picture was taken during Joint Investigation of 29<sup>th</sup> June 2017.



Close-up: Corrosion on Tunu Well 7T Wellhead at Agbidiama. Picture was taken during Joint Investigation of 29<sup>th</sup> June 2017.