


Overview: Part of spill impact on 20" Kolocreek-Rumuekpe Pipeline Right of Way at Odau. Picture was taken during Joint Investigation of 23rd August 2017.



Close-up: Illegal fittings on 20" Kolocreek-Rumuekpe Pipeline at Odau. Picture was taken during Joint Investigation of 23rd August 2017.