



Overview: Part of spill impact on 24" Nkpoku-Bomu Pipeline Right of Way at B-Dere. Picture was taken during Joint Investigation of 14th June 2018.



Close-up: Drilled Hole on 24" Nkpoku-Bomu Pipeline at B-Dere. Picture was taken during Joint Investigation of 14th June 2018.