


Overview: Part of spill impact on 10'' DiebuCreek– Nun River Pipeline Right of Way at Oporoma. Picture was taken during Joint Investigation of 27<sup>th</sup> June 2018..



Close-up: Hacksaw Cut on 10'' DiebuCreek– Nun River Pipeline at Oporoma. Picture was taken during Joint Investigation of 27<sup>th</sup> June 2018.