



Overview: Part of spill impact on 10'' DiebuCreek– Nun River Pipeline Right of Way at Oporoma. Picture was taken during Joint Investigation of 22nd June 2018.



Close-up: Leaking multiple Hacksaw Cuts on 10'' DiebuCreek– Nun River Pipeline at Oporoma. Picture was taken during Joint Investigation of 22nd June 2018.