


Overview: Part of spill impact on 14" Okordia-Rumuekpe Pipeline at Akaramini . Picture was taken during Joint Investigation of 3<sup>rd</sup> July 2018.



Close-up: Drilled Hole on 14" Okordia-Rumuekpe Pipeline at Akaramini . Picture was taken during Joint Investigation of 6<sup>th</sup> July 2018.